

NAGRA VI SERVICE BULLETIN FOR THE VERSION 3.03

*(Installation of this version **WILL NOT** erase the settings and internal templates of your machine)*

This is a brief explanations of the small corrections made since version V 3.02

- Bug correction: Using the 2 USB ports simultaneously could result in a crash of the recorder. (If keys were pressed on the USB keyboard while the USB storage media was being accessed.)
- Bug correction: With the time code set to 23.976 fps the external time code was not correctly recognized (in the TC display menu, sometimes the "External" indication would blink).
- Bug correction: Illogical selection on the inputs 5 and 6. Input 5 could be set to AES B and input 6 to a line input.

NAGRAVISION SA
Oct, 2010